


EXISTING CONDITIONS



INDEPENDENCE PARK IMPROVEMENTS

BEVERLY, MA | MAY 7, 2025



EXISTING CONDITIONS PHOTOS



WILSON AVENUE PARK ENTRANCE



EXISTING VIEW FROM LOTHROP STREET
SIDEWALK TOWARDS CENTER OF PARK



VIEW NORTH ALONG LOTHROP ST.



EXISTING BENCHES ALONG LOTHROP ST.



CENTRAL STREET PARK ENTRANCE



EXISTING MONUMENT



EXISTING CANNON AND PLAQUE



VIEW FROM EXISTING LOWER WALKWAY TOWARDS AREA OF
FUTURE STAIR CONNECTION



EXISTING STAIRS FROM LOTHROP



EXISTING STAIRS TO LOTHROP



VIEW LOOKING NORTH FROM CENTER OF PARK



VIEW LOOKING SOUTH FROM CENTER OF PARK

INDEPENDENCE PARK IMPROVEMENTS


OVERALL PROPOSED PLAN



INDEPENDENCE PARK IMPROVEMENTS


BEVERLY, MA | MAY 7, 2025

ENLARGED PROPOSED PLAN



INDEPENDENCE PARK IMPROVEMENTS

BEVERLY, MA | MAY 7, 2025




SURVEY OVERLAY ON OVERALL PROPOSED PLAN



INDEPENDENCE PARK IMPROVEMENTS

BEVERLY, MA | MAY 7, 2025



SURVEY OVERLAY ON ENLARGED PROPOSED PLAN



INDEPENDENCE PARK IMPROVEMENTS

BEVERLY, MA | MAY 7, 2025

